B.R. No: 158/Date: 31/05/2013

Inspection report for the work of : Providing Cement Concrete to Cross road at backside of Mahalakshmi temple Kalyannagara in Ward-13, in Shettyhalli Sub-Division

By

Sri. *G.M. Muniyappa*

Inspection Report

Name of Work	:	Providing Cement Concrete to Cross ... at backside of Mahalakshmi temple Kalyananagara in Ward-13, in Shettyhalli Sub-Division
Est. Cost	:	
B.R. No & Dated	:	158/Date: 31/05/2013
Agency	:	R. Niranjan
Bill Amount	:	10,45,113.72
Date of Inspection	:	19/05/15
Observations & Conclusions	:	

The above said site has been shown by the concerned Site Engineer. The Measurements are checked by me and it is found satisfactory

19/05/15

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Asst Engineer
Ward no.13

Name of works: providing cement concrete to cross Roads At Back Side of Mahalakshmi Temple Kalyana Nagar in ward NO NO-13 in Shetty halli Sub-Divn:

B.L.N.C

158/13-14

31-05-13



G.M.MUNIYAPPA
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

B.R. No: 158/Date: 31/05/2013

Name Of Work: Providing Cement Concrete to Cross road at backside of Mahalakshmi temple Kalyananagar in Ward-13, in Shettyhalli Sub-Division

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

B.R. No: 158/Date: 31/05/2013

Name Of Work: Providing Cement Concrete to Cross road at backside of Mahalakshmi temple Kalyananagara in Ward-13, in Shettyhalli Sub-Division

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT